

JOHNSONTOWN HISTORIC DISTRICT
937 Railroad Avenue (house)
Atlanta
Fulton County
Georgia

HABS No. GA-38-C

HABS
GA,
61-ATLA,
18-

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
Department of the Interior
Southeast Region
Atlanta, Georgia 30303

United States Department of the Interior
Heritage Conservation and Recreation Service
Washington, DC 20243

HABS GA, 61-ATLA, 18-
NATIONAL ARCHITECTURAL AND ENGINEERING RECORD
HISTORIC AMERICAN BUILDINGS SURVEY
ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VICINITY	
Georgia	Fulton	Atlanta	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			HABS NO.
JOHNSONTOWN HISTORIC DISTRICT			GA-38-C
SECONDARY OR COMMON NAMES OF STRUCTURE			
937 Railroad Avenue (house)			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)			
937 Railroad Ave.			
DATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)	
circa 1929 or after (1928 USGS Map)		Cliff Walker, relative of Henry Walker, did stone masonry on foundation	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)			
Although many of the details of this 2½ story structure are in keeping with the 20th century vernacular types in Johnseentown, the 1½ story random granite masonry base distinguishes the building. A community restaurant has been located here for several years and is still in operation.			
STYLE (IF APPROPRIATE)			
20th century vernacular			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)			
random course granite foundation; wood frame; hip roof with projecting eaves			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)			
does not apply			
EXTERIOR FEATURES OF NOTE			
3 story stair and accompanying entrance porches for the three levels; attached privy on rear; weatherboard is exterior siding material			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)			
does not apply			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES			
does not apply			
PRESENT CONDITION AND USE			
Building is in fair condition; six rental units in building; appears to be occupied			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)			
visual inspection; oral history; 1928 USGS Map; "A Community History of the Johnseentown Neighborhood"			
COMPILER, AFFILIATION			DATE
Steve Grable, Ann DeRosa Byrne The History Group, Inc.			May 1981